General Environmental Incident Summary

Incident: 1941 Date/Time Notice: 6/14/2013 0930 DEM Incident No:

Responsible Party: Healthcare Environmental Services

Date Incident: 6/14/2013 Time Incident: 0130 Duration: 2 hours

County: Cass Twp: 140 Rng: 49 Sec: 34 Qtr:

Lat: 46.89793 Long: -96.85099 Method: Derived from TRS

Location Description: 1420 40th St. N. Fargo ND

Submitted By: Miles Schacher Affiliation:

Address:

City: State: Zip:

Received By:

Contact Person: Chad Wold

1420 40th St. N. Fargo, ND 58102

Distance Nearest Occupied Building: 50 Feet

Type of Incident: Fire

Description of Released Contaminant: Unknown

Volume Spilled: Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

Smoke from the Healthcare Environmental Services incinerator filled the building after a malfunction of the ID fan. The plant went into burn down mode and ceased all operations at that time. Fargo Fire evacuated the building and found no fire in the building it was contained in the incinerator. The building was cleared to be entered at 0540 by David Roethel the Operations Manager who checked CO and oxygen levels and found them to be at safe levels for building entry. It was found that the dump stack remained closed throughout the entire incident so no hazardous smoke was emitted into the atmosphere. It was determined that an electrical issue cause the malfunction.

Risk Evaluation:

Inhalation hazard from potentially hazardous smoke.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 01 - air

Potential Environmental Impacts:

None because no smoke was released into the environment with the exception of venting the building.

Action Taken or Planned:

Red River Electric is fixing the electrical problem.

Friday, January 27, 2017 Page 1 of 2

Wastes Disposal Location: NA

Agencies Involved: Local Fire Department, State Health- Chris Roob

Updates

Date: 6/14/2013 Status: Reviewed - Assigned to NDDoH Division Author: Roberts, Kris

Updated Volume:

Notes:

No environmental release of smoke from the incinerator. Forwarded to Air Quality for any further investigation, if necessary.